

## Referenz: Model Hostinné Czech Republic


(Cardboard box manufacturer)

Comment from Customer: The machine and cutting plates were clean out for 3 hours – it was very dirty (a last cleaning two years ago made by BOBST)

Everything was OK. People (operators, guys from maintenance department, specialit for diecutters) were very satisfied with result.



VORHER/Before



Nachher/Afterwards

